

00862.022261

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re Patent of:

TAKASHI ARAI

Appln. No.: 09/877,092

Filed: June 11, 2001

For: FOAM MOLDING METHOD AND  
APPARATUS

U.S. Patent No.: 7,107,601 B2

Issued: September 12, 2006

)  
: Examiner: Mark S. Blouin  
)  
: Art Unit: 2627  
)  
:  
)  
:  
)  
:  
)  
:  
)  
: January 17, 2007

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Certificate**

JAN 23 2007

**of Correction**

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

01/19/2007 HMARZ12 00000185 7107601


01 FC:1811

100.00 00 OP

JAN 23 2007

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

  
Jason M. Okun  
Attorney for Patentee  
Registration No. 48,512

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200

611723v1

JAN 23 2007

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,107,601 B2

DATED : September 12, 2006

INVENTOR(S) : TAKASHI ARAI

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 9

FIG. 9, "FORM" should read --FOAM--.

SHEET 35

FIG. 34, "ELEXURAL" (both occurrences) should read --FLEXURAL--.

COLUMN 2

Line 11, "in" should read --at--; and

Line 17, "developed" should read --developed at--.

COLUMN 3

Line 32, "in" should be deleted.

COLUMN 4

Line 3, "use" should read --uses--.

COLUMN 5

Line 38, "characterized in that" (second occurrence) should be deleted.

COLUMN 13

Line 46, "andisconnected" should read --and is connected--; and

Line 57, "is" should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,107,601 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

611723v1



JAN 23 2007

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,107,601 B2

DATED : September 12, 2006

INVENTOR(S) : TAKASHI ARAI

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 18, "bubble" should read --bubbled--; and

Line 53, "no" should read --not--.

COLUMN 15

Line 8, "andiscontrolled" should read --and is controlled--.

COLUMN 16

Line 1, "andiscon-" should read --and is con---; and

Line 4, "andiscompletely" should read --and is completely--.

COLUMN 20

Line 62, "diameter" should read --diameter of--.

COLUMN 22

Line 63, "drum" should read --drum.--; and

Line 64, "Since" should read -- ¶ Since--.

COLUMN 24

Line 45, "20  $\mu$ was" should read --20  $\mu$ m was--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,107,601 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

611723v1



JAN 23 2007

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,107,601 B2

DATED : September 12, 2006

INVENTOR(S) : TAKASHI ARAI

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

Line 47, "a gas," should read --gasses,--.

COLUMN 26

Line 45, "molded product" should be deleted; and  
Line 52, "electric" should read --electrical--.

COLUMN 27

Line 7, "electric" should read --electrical--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,107,601 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

611723v1



JAN 23 2007

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,107,601 B2

DATED : September 12, 2006

INVENTOR(S) : TAKASHI ARAI

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 9

FIG. 9, "FORM" should read --FOAM--.

SHEET 35

FIG. 34, "ELEXURAL" (both occurrences) should read --FLEXURAL--.

COLUMN 2

Line 11, "in" should read --at--; and

Line 17, "developed" should read --developed at--.

COLUMN 3

Line 32, "in" should be deleted.

COLUMN 4

Line 3, "use" should read --uses--.

COLUMN 5

Line 38, "characterized in that" (second occurrence) should be deleted.

COLUMN 13

Line 46, "andisconnected" should read --and is connected--; and

Line 57, "is" should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,107,601 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

611723v1



JAN 23 2007

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,107,601 B2

DATED : September 12, 2006

INVENTOR(S) : TAKASHI ARAI

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 18, "bubble" should read --bubbled--; and  
Line 53, "no" should read --not--.

COLUMN 15

Line 8, "andiscontrolled" should read --and is controlled--.

COLUMN 16

Line 1, "andiscon-" should read --and is con---; and  
Line 4, "andiscompletely" should read --and is completely--.

COLUMN 20

Line 62, "diameter" should read --diameter of--.

COLUMN 22

Line 63, "drum" should read --drum.--; and  
Line 64, "Since" should read -- ¶ Since--.

COLUMN 24

Line 45, "20  $\mu$ was" should read --20  $\mu$ m was--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,107,601 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

611723v1



JAN 23 2007

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,107,601 B2

DATED : September 12, 2006

INVENTOR(S) : TAKASHI ARAI

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

Line 47, "a gas," should read --gasses,--.

COLUMN 26

Line 45, "molded product" should be deleted; and

Line 52, "electric" should read --electrical--.

COLUMN 27

Line 7, "electric" should read --electrical--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,107,601 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

611723v1



JAN 23 2007